

SX-7050 Layout

1.3 Overall drawing for main dimensions




Fig. 1-2. Top view of machine

Note: Space required for operation is at least 1 meter away from every side edge.